

Oil Field Environmental Incident Summary

Incident: 20140627094822 **Date/Time of Notice:** 06/27/2014 09:48

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: LOSTWOOD 10-2227H

Field Name: KITTLESON SLOUGH

Well File #: 20220

Date Incident: 6/26/2014 **Time Incident:** 15:00

Facility ID Number:

County: MOUNTRAIL

Twp: 158

Rng: 91

Sec: 22

Qtr:

Location Description:

Submitted By: Matt Richards

Received By:

Contact Person: Matt Richards
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Stuffing Box Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.8	Barrels	0.8	Barrels	0.8	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 10/19/2015

Clean Up Concluded: 6/29/2014

Risk Evaluation:

None

Areal Extent:

8' x 90'

Potential Environmental Impacts:

None

Action Taken or Planned:

Booms were put down to prevent oil running off site due to inclement weather in are. When conditions permit D&L will clean up and remove contaminated soil. The landowner was contacted about the spill and wants the field left alone at this time. We will continue to monitor crop for any stresses.

Wastes Disposal Location: Clean Harbors

Agencies Involved:**Updates**

Date: 6/27/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from a stuffing box leak sprayed off location. However, landowner doesn't want the impacted field disturbed at this time. Will evaluate and document at this time and contact landowner if impact is severe.

Date: 7/1/2014 **Status:** Inspection

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

7/1/14 - 11:00 on location. Description and response as reported. Multiple absorbent booms across the northside perimeter ditch, which leads to a small, unimpacted depression to west near a tree line. Wet weather conditions have hampered the on-location cleanup. There are several hundred square feet of impacted crop in the field north of the perimeter ditch, evidenced by curling leaves and few if any blossoms on the plants in relation to the rest of the field. No further NDDoH inspection is needed at this location. Company and landowner will coordinate the balance of the restoration.

Date: 4/18/2016 **Status:** Correspondence

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated April 18, 2016.